G. R. S. 59]

GPB—15,000—22-7-14

GENERAL AND REVENUE SECRETARIAT.

1901-02

~~191~~.

(L. B)

File No. 6 of 1901

Serial Nos. 1—6

B

~~**Papers Filed.**~~

Month December 1902

Countermarked

SUBJECT.

Sinking of a well at Bhavikere in the Tarikere taluk.

Indexed

[illegible]

PREVIOUS REFERENCES.	LATER REFERENCES.

DEWAN'S OFFICE.

GENERAL DEPT.—(L. B. BRANCH).

OFFICE NOTE.

SUBJECT.

Grant of a further sum of Rs 317 from L.F. General for sinking a well at Bhavikere in the Tarikere Taluk.

SECTION L.B.

FILE No. 6 of 01

SERIAL No. 1—6

LAST REFERENCE

(8C1)

Letter No. 825 dated 8th May 1902

from the President D.F. Bd Kadur.

An estimate for Rs 475 was sanctioned by the President of the L.F. Bd Kadur Circle for sinking a well at Bhavikere in the Tarikere Taluk from the grant of Rs 3384 sanctioned from L.F. General in Pro No. 3350-1 / L.F. 2-98 of 7-9-99.

~~Sl No 63~~ (Encl B to 8C6)

As only a sum of Rs 283-13 was spent on the work up to the

MGCPB—250—18-3-02

1901.

End of June ~~[illegible]~~

[illegible]

~~[illegible]~~ May the President be requested to submit a revised estimate ~~[illegible]~~ ~~total cost~~ for the formal sanction of Govt and to state whether the total expenditure was incurred and the work completed.

[illegible] 31/5/02 [illegible]

[illegible] 11/6/02 7/1/1902 Yes [illegible] 11/6

in question was sunk to
a depth of 45 feet accord-
ing to the original estimate,
it was found absolutely
necessary that it should
be deepened 5 feet more
to ensure a permanent
supply of water, and re-
vetted with stones the
whole depth, as the soil
was very loose; that, as
the monsoon was
approaching, the work
could not be stopped at
that stage and it was
pushed on to completion
by the Amildar of the
Tarikere Taluk, as other-
wise the amount already
spent on the well would
have been wasted, and
the well would have
been of no use to the
public, and that payment
for the work is not yet
made awaiting sanction
of Government

A

Read:—

Letter No. 525 dated 8th May 1902 from the President of the D.F. Board Kadur circle, stating that an estimate for Rs 475 was sanctioned by him for sinking a well at Bhavi kere in the Tarikere Taluk from the grant of Rs 3384/- sanctioned from L.F. General in Proceedings No. 3350-1 / LF 2-98 of 7th September 99, that as only a sum of Rs 283-13 was spent on the work up to the end of June 1901 a grant of Rs 191 was sanctioned in Proceedings No. 8412-20 / LF 29-00 of 3rd 12-01 and requesting a further grant of Rs 317 for revetting the whole depth of the well with stones, as the soil was found to be loose.

(2) ~~Read~~ Letter No. 31 of 4th July 02 from the same officer stating with reference

(~~Short note~~) ~~Ex~~

+ Draft for approval.

29/8

The Dewan through the 2nd Councillor.

(Sl 63)

(Spare copy put up)

to the office No 19546 of
L42 98

(sl 77)

23 June 1902, that the
work has been reported
to have been completed
and submitting a
revised estimate
for Rs 792 for the work.

3 Letter No 2438 3rd Novr 1902 from the
same office furnishing, with reference to this
office No 3153 d 3rd Novr 1902, explanation for having
incurred excess expenditure on the well in
question.

Order thereon :—

The revised
estimate for Rs 792 for
sinking a well at Bhavi
Dee in the Tarikere Taluk
is sanctioned.

2) The balance
Rs 342 still to be paid
will, as a special case,
be met from L 4 fund.

This has to be submitted
to the Dewan who passed
the order of 7/12/01

I cannot sanction Dy 29/7
this. Such works
without proper
sanction are
increasing in spite
of the repeated orders
that officers concerned
who incur personal
liability. I do not
know why sanction
should have
been obtained
before &

Secretary
Dy 29/7/02

To the Tahsildar Bhadra
with Dewan's Estimate
[illegible]
[illegible]

Pendulum was
incurred. Who
is the officer
what is his
[illegible]

6906
6902

was accordingly done so.

The amildar of the Sirikere Taluk reports that there is 8 ft of good water at this season of the year, that the villagers are using it and that the soil at the bottom having been found to be very loose, the whole depth of 50 ft was found to be revetted with stones, to which a revised estimate is submitted for sanction.

The above revised estimate together with the marginally noted enclosures is herewith sent with a request that a further grant of Rs 317/- may be kindly sanctioned from Local Funds General, as the grant of Rs 191/- available for this Work, sanctioned in G.O. No. 8412-20 L.R. 29-00 of this 3rd December 1901 is only for the balance of Work as per original Estimate.

1 Original Estimate for Rs 475/-
2 Comparative Statement
3 Abstract of the revised Estimate
4 Plan of the Well

* Vide L.B. 3201 Sl. 12

I have the honor to be,
Sir,
Your most obedient Servant,
[signature]
President of the
Local Funds Board
Kadur Circle.

Sir

L. F. 56.] Estimate of the Probable Cost of (6) 2

Detail of works	No.	Dimensions			Contents	Total
Earth Work Excavation						
gravelly soil	1	$(12)^2$	·7854	3	339	12½
Soft Rock	1	$(12)^2$	·7854	9	1017	37⅔
Rock cutting	1	$(6)^2$	·7854	13	367	13½
Blasting Rock	1	$(6)^2$	·7854	15	424	15⅔
Soft Rock at the bottom	1	$(6)^2$	·7854	10	282	10
Widening the sides	1	(12)	·7854	38	4297	
Deduct Earth work already done	1	$(6)^2$	·7854	38	- 1074	
			Bal.		3223	118½
Baling water	L.S.					10
Rough Stone Lining	1	$(10\frac{1}{3})^2$	·7854	50	4193	
Deduct dimensions of the well portion	1	$(4\frac{1}{3})^2$	·7854	50	- 737	
			Bal		3456	128
Burnt Stone Slabs						
At the bottom & top	2	$(7\frac{1}{3})^2$	·7854	(6)	84	
Deduct dimensions of the well portion	2	$(4\frac{1}{3})^2$	·7854	(6)	- 29	
					55	
Pillars	2	8	1¼	6	20	
			Total		75	75
Earth filling behind the rough stone lining	1	$(12)^2$	·7854	50	5654	
Deduct well portion	1	$(10\frac{1}{3})^2$	·7854	50	- 4193	
					1461	54
Burnt brick in Chunnam						
Parapet Wall	1	$(7)^2$	·7854	3	115	
Deduct well portion	1	$(4\frac{1}{3})^2$	·7854	3	- 44	
					71	71

(Contd)

Chunnam Plastering

external portion	1	22	.	3	66	
Internal portion	1	13½	.	3	40	
				Total	106	
Coping	1	$(7)^2 \cdot 7854$			38	
deduct well portion	1	$(4\frac{1}{3})^2 \cdot 7854$			-14	
					24	
Total Chunnam Plastering					130	130
Teak wood beams	1	12	2/3	3/4	6	6
wooden pulleys with iron work complete	1	-	-	-	-	1
Burnt Stone slabs dressed	12	-	-	-	-	12
" pillars — do —	2	-	-	-	-	2

Revised Estimate for Sinking a circular drawing well at Bhawikere in the Tarikeri Taluk — Ex. W J C

Abstract

Items	Per	Rate		Quantity	Amount	
1. Earth Work, Excavation Gravelly Soil	C yds	-	6	12½	5	-
2. — do — Soft work	— do —	1	8	37⅔	57	-
3. Rock cutting	— do —	3	-	13½	40	8
4. Blasting rock	— do —	4	8	15⅔	70	-
5. Soft rock excavation	— do —	2	-	10	20	-
6. Widening the sides	— do —	2	-	118½	237	-
7. Baling Water	L.S.	-	-		10	-
8. Rough Stone Lining	Sq. ft	2		128	256	-
9. Burnt Stone Slabs	— do —	-	8	75	38	-
10. Earth filling behind the Stone lining	C. yd	-	2	54	7	-
11. Burnt brick in chunam	C ft	-	4	71	18	-
12. Plastering with chunam	sqre	4	-	1:30	5	-
13. Teak Wood Beam	C ft	2	-	6	12	-
14. Pulley's with Iron work Complete	1	2	8	1	2	8
15. Dressing the burnt Stone Slab	1	1	-	12	12	-
16. — do — Stone posts.	1	1	-	2	2	-
				Total	792	-
Deduct the amount of the Original Estimate					Rs 475	-
Net amount to be Sanctioned					Rs 317	-

Rupees Three hundred and seventeen only.

Dated, Chikamagalur
8th May 1902

[signature]
President
Local Fund Board
Kadur Circle

Revised Estimate for sinking a circular drawing well at Bhavikere in the Tarikere Taluk.

Abstract

	Items	Per	Rate		Quantity	Amount	
1.	Earth Work Excavation Gravelly Soil	Cyds.	"	6 "	12½	5 "	"
2	— do — Soft rock	cyds.	1	8 "	37⅔	57 "	"
3	Rock cutting	-do-	3	" "	13½	40 8	"
4.*	Blasting Rock	-do-	4	8 "	15⅔	70 "	"
5	Soft rock excavation	-do-	2	" "	10	20 "	"
6.	Widening the Sides	-do-	2	" "	118½	237 "	"
7	Baling Water	L.S.	-	-	-	10 "	"
8	Rough Stone lining	sq ft	2	" "	128	256 "	"
9	Burnt Stone Slabs	-do-	"	8 "	75	38 "	"
10	Earth filling behind the Stone lining	cyd.	"	2 "	54	7 "	"
11	Burnt brick in Chunnam	cft	"	4 "	71	18 "	"
12	Plastering with Chunnam	sqre	4	" "	1.30	5 "	"
13	Teak Wood beam	cft	2	" "	6	12 "	"
14	Pulleys with iron Work complete	1	2	8 "	1	2 8	"
15	Dressing the burnt Stone Slab	1	1	" "	12	12 "	"
16	do — Stone posts	1	1	" "	2	2 "	"
					Total	792 "	"

Deduct the amount of the original Estimate Rs. 475 " "

Net amount to be Sanctioned 317 "

Rupees three hundred and Seventeen only

Dated Chikmagalore
8th May 1902

President
Local Fund Board
Kadur Circle

ಅಂಬ್ಲಿ ಅಕ್ಕಿಕೆರೆ — ದಿವ್ಯಕೆಂಚಕೆರೆ ರಾಂಬ

ಅಂದರೆ ಸ್ಟೂ ಅಕ್ಕಿಕೆರೆ ರಾಂಬ ಅಕ್ಕುಂಬಳ್ಳಿಕೆರೆಯಾಯಿತೆಂದು ಬಾಂಗಳೆಕೆ

ಸ್ಟೂ ಪೆಂಬಳ್ಳಿ ಕೆರೆಗಳಿಗೆ ಸಂಬಂಧಪಟ್ಟದ್ದು ಬಾಂಗಳೆಂಸಂಖ್ಯೆಗಳು ಸೇರಿ

1899. 1900 ನೆಯ ಇಸ್ವಿ.

ಕೆರೆ ಬಿಲ್ಲು

ಕೆಂಸಂಖ್ಯೆಗಳು	ಗುಂ	ಅಳತೆ			ಸಂಖ್ಯೆ	ಒಟ್ಟು
ಬಾಂಗಳೆಸಂಖ್ಯೆ						
ಪೆಂಬಳ್ಳಿ ಬಾಂ ಸಂಬಂಧಪಟ್ಟಿದ್ದು						
ಬೆಂಬಳ್ಳಿ ಉದ್ದ	1	12^2	.7854	12	1357	50
ಉದ್ದಕ್ಕೆ ಸ್ಟೂ ಕೆರೆ ಅಕ್ಕಿಕೆರೆ ಅಗಲ	1	12^2	.7854	12	1357	50
ಇಳಿಯ ಸಮ್ಮಿಶ್ರಿಯಾಗಿ ಸಿಕ್ಕಿದಂತೆ ಮೇಂಬಾಗ						
ಅಂಕಿಸಂಖ್ಯೆಗಳು ಅಂಬಳಂಬಾಂಗಳು	1	6^2	.7854	21	593	22
ಕಡೆಕೆಲ್ಲ ಕೆಲಸಗಳು						
ಇಳಿಸಾಲುಗಳ ಉದ್ದ	1	12^2	.7854	27	3053	
ಉದ್ದಕ್ಕೆ ಬಾಂ ಉದ್ದ	1	6^2	.7854	27	763	
ಬಾ ಅ ಬಾಕಿ					2290	84
ಸ್ಟೂಬ್ಬ ಕೆಲ್ಲ ಚರಡಿ ಕೆಲ್ಲ						
ಬಾ ಇಳಿ ಅಕ್ಕಿಕೆರೆಗೆ ಕೆಲಸ ಕೆಲಸಕ್ಕೆ ಸಂಖ್ಯೆ	2	10^2	.7854	(6)	156	
ಉದ್ದಕ್ಕೆ ಬಾ ಉದ್ದ	2	6^2	.7854	(6)	56	
ಬಾಕಿ					100	
ರಾಂಚಿ ಸೀಂಸ್ಟರ ಕೆಲ್ಲ ಬಾಂ ಸಂಖ್ಯೆ	2	8	1¼	(6)	20	
ಅಂ ಸ್ಟೂ					120	120
ಸ್ಟೂಬ್ಬ ಉಂಬ ಸಿ ಸ್ಟೂಂಗ್ಲ ದ ಕೆಲ್ಲ						
ಕೆಲಸಕ್ಕೆ ಸಂಬಂಧಪಟ್ಟ ಕೈವಿರಿ ಸೀಸ್ಟ್ರಕೆ	1	9^2	.7854	3	190	
ಉದ್ದಕ್ಕೆ ಬಾ ಉದ್ದ	1	6^2	.7854	3	84	
ಬಾಕಿ					106	106
ಸ್ಟೂಗ್ಲದ ಸಿಲಾ ಕೆ. ಸ್ಟೂಬಾಂ						

[illegible]	1	28		3	84	
[illegible]	1	19		3	57	
[illegible]	1	9^2	.7854	.	65	
[illegible]	1	6	.7854	.	28	
					35	
					1.76	1.76
[illegible]	1	12	2/3	3/4	.	6
[illegible]	2	.	.	.	.	2
[illegible]					.	2
[illegible]	16	.	.	.	.	16
[illegible]					.	.90

[illegible]

[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]
1.	Earth work soft [illegible]	cyds. [illegible]	0 6 0	50	19 — 0
2.	[illegible] hard. [illegible]	[illegible]	0 12 0	50	37 — 0
3.	Blastering rock [illegible]	[illegible]	4 8 0	22	99 — 0
4.	Rough stone work [illegible]	[illegible]	2 0 0	84	168 — 0
5	Burnt stone stabs [illegible]	Sq ft [illegible]	0 8 0	120	60 — 0
6.	plastering with mortor [illegible]	[illegible]	4 0 0	1.76	7 — 0 0
7.	Parapet wall Burnt brick with morter [illegible]	cyds. [illegible]	0 4 0	106	26 — 0 0
8	Teak wood beam [illegible]	[illegible]	2 0 0	6	12 — 0 0
9.	pullies [illegible] 2.	1 [illegible]	2 8 0	2	5 — 0 0
10	Dressing stone pillers [illegible]	1 [illegible]	1 0 0	2	2 — 0 0
11	Spreading rough [illegible] Dressing burnt stone stabs [illegible]	1 [illegible]	1 4	16	20 — 0 0
12	Bailing water L. S. [illegible]				20 — 0 0
				[illegible]	475 0 0
	[illegible] 10/- [illegible]				~~47 — 0 0~~
	[illegible]				~~522 — 0 0~~

[illegible] 9. 1. 1900 [illegible]

[illegible]

[illegible]

[illegible]

Sanctioned for Rupees four hundred & Seventy five only

[illegible]

President of the L. G. Board

Chikkaballapur
29th January 1900

లక్కువళి శిలాబళి మోజే భావికేరి గ్రామదభావికేలసానడదబత్రే ప్లాన్.





బిల్లనంబర 1 నేదరల్ల ఇకేలసానడద్దు

బిల్లనంబర 2 నేదరల్ల ఇకేలసానడద్దు

కనత్తు కేరాంతు బిల్లువ భాగవు

బిల్లనంబరు 3-4 రల్ల కేలసానడద్దు. ఆందరే పున: ఆజమాఇతిమా దువల్ల 15 ఆడిప్రాలా తవావలకండబందద రిందాఱ్ఱిందా సవల మేంటె ఆందాళాదల్లదాంతు బిల్లనంబర 5 నేదరల్లవజా మాడిరుత్తే.

[signature]
President

[signature]
[illegible]

Comparative statement shewing the abstract of the estimate for sinking a circular drawing well at Bhavikere in the Tarikere Taluk

No.	Name of work	Establishment as originally sanctioned		Estimate as now revised		Difference				Net amount required for the work	Remarks
						Less		More			
		Quantity	Amount	Quantity	Amount	Quantity	Amount	Quantity	Amount		
1	Excavation gravelly Soil	50	19	12½	5	45	14				
		"	"	"	"	"	"				
2	— Do — Soft Rock	50	37	37⅔	57				20		
3	Rock cutting			13½	40 8			13½	40 8		
4	Blasting Rock	22	99	15⅔	70 8	6⅓	28 8				
5	Soft rock excavation			10	20			10	20		
6	Excavating & Widening the Sides			118½	237			118½	237		
7	Baring water		20		10		10				
8	Rough stone lining	84	168	128	256			44	88		

9	Burnt stone slabs	120	60	..	75	38	..	45	22	..	.	...
10	Earth filling behind the stone lining	.	...		54	7	..	.	...		54	7 ..
11	Burnt Brick in chunnam	106	26	..	71	18	..	35	8	..	.	...
12	Plastering with chunnam	176	7	..	130	5	..	46	2	..	.	...
13	Teak wood beam	6	12	..	6	12	..	.	...		.	...
14	Pullies with iron works complete	2	5	..	1	28	.	1	28	.	.	...
15	Dressing the B. S. slab	16	20	..	12	12	..	4	8	..	.	...
16	Do. Stone posts	2	2	..	2	2	..	.	...		.	...
	Grand Total		475	..		792	..		95	..	4128	317

Chickmagalur
Dated 8th May 1902

President of the
Local Fund Board
Kadur circle

18 ~~79~~ (2)

To
The President
of the D. F. Board,
Kadur L.B. circle,

SECTION R. B.
FILE No. 6 of 1901
SERIAL No. 9

His letter No. 825 dated 8th May 1902, soliciting the grant of a further sum of Rs 317 from L. F. General, for sinking a well at Bhavikere in the Tarikere Taluk.

R.L. 2033.

19546.
L. F. 2-98 of 23/6/1902

From the Same
31 of 4/7/02 L98

With reference to the above, has the honour to request that the President will be so good as to submit a revised estimate for the formal sanction of Government, and to state whether the total expenditure was incurred and the well completed -

By order

4/6/02 For Secretary
12/6/02

2/

(9

has been deferred for want of funds. The well work is reported by the Amildar to have been com-
-pleted satisfactorily.

I have the honor to be,

Sir,

your most obedient servant.

President of the
Local Fund Board
Kadur Circle

Compd

18 14

To
The President
D. F. Board,
Kadur Circle

L. B.
6801
4

R.L. 436.

No 3753 / L.F. 29-00 & 12/9/1902

His letter No. 31 dated 4th July 1902, submitting a revised estimate for Rs 792 for sinking a well at Bhavikere in the Tarikere Taluk.

792
475
317

With reference to the above, has the honor to observe that such works without proper sanction are increasing in spite of the repeated orders that officers concerned would incur personal liability.

The President is requested to be so good as to state why sanction was not obtained before the expenditure was incurred, ~~He should also~~ ~~He should also report the name of~~

who is responsible for such expenditure & to obtain ~~[illegible]~~
~~the [illegible]~~

Submit his explanation

for the orders of Govern-

ment.

By order

[illegible]
10/9/1902
for Sec.

(Dewan's order

Spare copy stitched to this letter (marked A)

No: 9177-85 / L.F. 137-92 dated 8th February 1896, Mr. B. K. Venkatvaradiengar the then Deputy Commissioner and President, Sanctioned an Estimate for Rs 475/- out of the Local Funds general grant of Rs 3384/- sanctioned in Government Order No

Do (Marked B)

X Vide Enclosure to Sl. 1

3350-1 / L.F. 2-98 of the 7th September 1900. A sum of Rs 283-13-0 was spent on the well work during the year 1900-1901 and the work was brought on the list of incomplete works submitted to Government and for the completion of which a grant of Rs 191/- was sanctioned in Government

Δ Do (Marked C)

Δ X Vide L.B. 3 of 01 Sl. 12

Order No 8412-20 / L.F. 29-1900 dated 3rd December 1901. When the work was carried out to a depth of 45 feet as per original Estimate, it was found absolutely necessary that the well should be deepened 5 feet more too ensure a permanent supply of water for the use of the public and to revet with stones the whole depth of 50 feet as the soil was very loose A revised Estimate was therefore prepared and submitted to Government for sanction with this office letter no 825

of

of the [illegible] May 1902. As the monsoon was approaching the work could not be stopped at that stage and it was therefore pushed on to completion to avoid loss to government. But payment is not yet made awaiting government sanction.

From the above it may be observed that owing to some unforeseen circumstances the additional work had to be undertaken by the Taluk Amildar to prevent the loss of the amount already spent and in the interest of the public.

I have the honor to be,
Sir
your most obedient servant

[illegible]
President of the
Dt Fund Board
Kadur Circle

Aml